

PATENT Customer Number 22,852 Attorney Docket No. 10189.0001-00

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 7,301,357)	
Inventors: Dai SHINOZAKI et al.)	
Issue Date.: November 27, 2007)	
For: INSPECTION METHOD AND INSPECTION EQUIPMENT))	Cerificate
		DEC 2 7 2007
Commissioner for Patents P.O. Box 1450		C. Carres. J.

Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 255, and 37 C.F.R. § 1.323, this is a request for a Certificate of Correction in the above-identified patent. The mistake(s) identified in the appended Form are of a clerical or typographical nature, or of minor character, and resulted from an error made in good faith by patentee(s). The Commissioner is hereby authorized to charge the \$100 fee set forth in 37 C.F.R. § 1.20(a) to Deposit Account 06-0916.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

> 12/21/2007 CNGUYEN2 00000017 060916 7301357 01 FC:1811 100.00 DA

Please charge any required fees not included herewith to Deposit Account 06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW, GARRETT & DUNNER, L.L.P.

Dated: December 19, 2007

Brad C. Rametta Reg. No. 54,387 (404) 653,6552

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,301,357

APPLICATION NO.:

10/538,785

ISSUE DATE:

November 27, 2007

INVENTOR(S):

Dai SHINOZAKI et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 6, column 7, lines 19-22, "tester, circuit, the drivers being connected to the respective pairs of probe pins to apply the drivers applying a voltage, which causes a fritting phenomenon to the respective electrodes," should read --tester, the drivers applying a voltage, which causes a fritting phenomenon, to the respective electrodes,--.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,301,357

APPLICATION NO.:

10/538,785

ISSUE DATE:

November 27, 2007

INVENTOR(S):

Dai SHINOZAKI et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 6, column 7, lines 19-22, "tester, circuit, the drivers being connected to the respective pairs of probe pins to apply the drivers applying a voltage, which causes a fritting phenomenon to the respective electrodes," should read --tester, the drivers applying a voltage, which causes a fritting phenomenon, to the respective electrodes,--.